


Materiał / Material

ST 37

Jak zamówić / How to order

Symbol: **BPS.100.300**

Sruby V8 / V12 str. J144  
Screws V8 / V12 page J144



Symbol	Symbol GSB	A <sub>1</sub>	L	L <sub>1</sub>	L <sub>2</sub>	B	B <sub>1</sub>	Forma Form
BPS.070.100	G234-01-070-100	70	100	50	-	20	-	A
BPS.070.150	G234-01-070-150	70	150	50	-	10	-	B
BPS.070.200	G234-01-070-200	70	200	50	-	20	-	D
BPS.100.100	G234-01-100-100	100	100	25	25	30	20	F
BPS.100.150	G234-01-100-150	100	150	50	25	50	-	C
BPS.100.200	G234-01-100-200	100	200	50	-	50	-	D
BPS.100.250	G234-01-100-250	100	250	50	-	50	-	E
BPS.100.300	G234-01-100-300	100	300	50	-	50	-	H
BPS.150.100	G234-01-150-100	150	100	50	-	25	50	G
BPS.150.150	G234-01-150-150	150	150	25	50	25	50	I
BPS.150.200	G234-01-150-200	150	200	50	-	100	-	D
BPS.150.250	G234-01-150-250	150	250	50	-	100	-	E
BPS.150.300	G234-01-150-300	150	300	50	-	100	-	H
BPS.200.100	G234-01-200-100	200	100	50	-	50	50	G